



PRODUCTION INSTRUCTION OF PO - 1926 / AO-AOR-13 / BUTTER FLY (61520)

DESCRIPTION	26*26
Party Quality	1350
Party Weight	0.589
Production Quality	1376
Production Weight	0.6
Pile Height - A	
Pile Height - B	
Pile Height - C	
Stitching 10 Cm A	
Stitching 10 Cm B	
Stitching 10 Cm C	
Width in Line 5 cms	
Niddle Gape / Weaving Com	
1. Yarn UV/Non UV	
2. Canvas UV/Non UV	CANVAS 56-600 GSM NU
3. Canvas Size	26*26
4. Canvas Quality	
5. Canvas Weight @ PC.	0
6. Canvas Cutting Size	
7. Pipen Tanki Fold	
8. Stiching in 5 CMS	
9. Pipen Folder MM	
10. Latex	
11. Export Packing	

12. Carving	
TUMBLER / WASHING	
PC DYEING WEIGHT	
PC WASHING WEIGHT	
TUMBLING WEIGHT	.590
TUFFTING FINAL WEIGHT	
EXTRA WORK WEIGHT	
ORDER QUANTITY	700