



PRODUCTION INSTRUCTION OF PO - 1886 / AO-S E-16 / RT-17285 CHECK

DESCRIPTION	60*100	70*120	80*150	45*50	50*90	75*75	50*80	47*50
Party Quality	1800	1800	1800	1800	1800	1800	1800	1800
Party Weight	1.081	1.511	2.158	.404	.809	.794	.675	.400
Production Quality	1974	1974	1974	1974	1974	1974	1974	1974
Production Weight	1.185	1.655	2.360	.450	.890	.870	.775	.470
Pile Height - A	0	0	0	0	0	0	0	0
Pile Height - B	0	0	0	0	0	0	0	0
Pile Height - C	0	0	0	0	0	0	0	0
Stitching 10 Cm A	0	0	0	0	0	0	0	0
Stitching 10 Cm B	0	0	0	0	0	0	0	0
Stitching 10 Cm C	0	0	0	0	0	0	0	0
Width in Line 5 cms	0	0	0	0	0	0	0	0
Middle Gape / Weaving Com	0	0	0	0	0	0	0	0
1. Yarn UV/Non UV	UVC	UVC	UVC	UVC	UVC	UVC	UVC	UVC
2. Canvas UV/Non UV	UVC	UVC	UVC	UVC	UVC	UVC	UVC	UVC
3. Canvas Size	70 INCH	70 INCH	70 INCH	70 INCH	70 INCH	70 INCH	70 INCH	70 INCH
4. Canvas Quality	.650 GSM	.650 GSM	.650 GSM	.650 GSM	.650 GSM	.650 GSM	.650 GSM	.650 GSM
5. Canvas Weight @ PC.	0	0	0	0	0	0	0	0
6. Canvas Cutting Size	0	0	0	0	0	0	0	0
7. Pilen Tanki Form	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE
8. Sticking in 5 CMS	0	0	0	0	0	0	0	0
9. Pilen Folder	MMS PER SAMPLE	MMS PER SAMPLE	MMS PER SAMPLE	MMS PER SAMPLE	MMS PER SAMPLE	MMS PER SAMPLE	MMS PER SAMPLE	MMS PER SAMPLE
10. Latex	NO	NO	NO	NO	NO	NO	NO	NO
11. Export Packing	NO	NO	NO	NO	NO	NO	NO	NO

12. Carving	NO	NO	NO	NO	NO	NO	NO	NO
TUMBLER / WASHING	NO	NO	NO	NO	NO	NO	NO	NO
PC DYEING WEIGHT	1.175	1.645	2.350	.440	.880	.860	.762	.460
PC WASHING WEIGHT	0	0	0	0	0	0	0	0
TUMBLING WEIGHT	0	0	0	0	0	0	0	0
TUFFTING FINAL WEIGHT	1165-1116	1355-1265	1550-2.34	180-.458	170-.898	150-.870	150-.774	150-.470
EXTRA WORK WEIGHT	0	0	0	0	0	0	0	0
ORDER QUANTITY	59	119	84	161	109	64	52	26